

OFF SITE WORKS



Temporary bridge across side channel, installed 11/10 after a shower of rain
[16/10]



Spoil was deposited on arable field. Large stone was removed by hand either at meadow or field end
[16/10]



Spread soil ploughed in
[07/12]



Spread soil ploughed in
[07/12]



Final stages of re-instating side channel approaches; recovered large flint was used in cattle crossing 3
[07/12]



Small stone recovered was used to re-instate stream bed at the crossing, and Extend upstream and (shown) downstream
[07/12]